


## Vehicle History Report<sup>™</sup>

US \$39.99

# 2019 MERCEDES-BENZ SPRINTER 3500/4500

VIN: WDAPF4CD8KN027149 CHASSIS AND CAB 3.0L V6 F DOHC 24V DIESEL REAR WHEEL DRIVE



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/22/20 at 7:51:01 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Ownership History The number of owners is estimated	🚨 Owner 1
Year purchased	2020
Type of owner	Lease
Estimated length of ownership	1 month
Owned in the following states/provinces	Florida
Estimated miles driven per year	
Last reported odometer reading	5

🚨 Owner 1
Alert! Problem Found
No Problem



**ALERT!** - Severe problems were reported by a state Department of Motor Vehicles (DMV). This vehicle does not qualify for the CARFAX Buyback Guarantee.

CARFAX Additional History  Not all accidents / issues are reported to CARFAX	🍰 Owner 1
Total Loss No total loss reported to CARFAX.	No Issues Reported
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	✓ No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	No Issues Reported
Odometer Check No indication of an odometer rollback.	No Issues Indicated

Accident / Damage DMV title problems reported.	Severe Damage
Manufacturer Recall At least 1 manufacturer recall requires repair. Most recalls can be repaired free of charge.	Recall Reported
Basic Warranty Original manufacturer warranty likely voided by manufacturer after vehicle was severely damaged.	Warranty Voided

## CARFAX Detailed History

Owner 1 Purchased:	2020		Lease Vehicle	
Mile	eage	Source	Comments	
03/31/2020	5	Florida Motor Vehicle Dept. Satsuma, FL	Odometer reading reported	
04/29/2020		Florida Motor Vehicle Dept. Satsuma, FL Title #0138415477	First owner reported - JUNK TITLE/CERTIFICATE ISSUED - Titled or registered as lease vehicle - Vehicle color noted as White	
05/06/2020		Auto Auction	Vehicle offered for sale	
05/18/2020		Mercedes-Benz USA LLC	Manufacturer Safety recall issued - NHTSA #20V180 - Recall #2020040019 - Status: Remedy Available	
			Click here or call 1-800-367-6372 to locate an authorized Mercedes-Benz dealer near you to obtain more information about this recall	
			<ul> <li>Learn more about this recall</li> </ul>	

**Description:** Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz and Freightliner vans, has determined that the operator's manual in certain Sprinter vehicles from platform 907 (VS30) with automatic transmission does not correctly specify certain conditions under which the automatic parking function ("Auto-P") operates. The Operator's Manual describes certain functions which would automatically engage the park position "P" if (1) the driver opens the seat belt buckle or (2) the driver leaves the seat when the vehicle is stationary or driving at very low speed. However, this functionality is not available in the affected Sprinter vehicles. Should a customer rely on the Auto-P function as described in the Operator's Manual, the possibility of vehicle rollaway or movement cannot be ruled out which could increase the risk of a graph. An authorized Marcodos-Renz or Frightling Sprinter dealer will add a supplementary increase the risk of a crash. An authorized Mercedes-Benz or Freightliner Sprinter dealer will add a supplementary booklet with a correct description of the Auto-P function to the Operator's Manual, which is already in the vehicle. The supplementary booklet is also available on-line at www.mbvans.com/sprinter/owners-resources/owner-manuals and https://www.freightlinersprinterusa.com/freightliner/owners-resources/owner-manuals.

The Operator's Manual describes certain functions which would automatically engage the park position "P" if (1) the driver opens the seat belt buckle or (2) the driver leaves the seat when the vehicle is stationary or driving at very low speed. However, this functionality is not available in the affected Sprinter vehicles. Should a customer rely on the Auto-P function as described in the Operator's Manual, the possibility of vehicle rollaway or movement cannot be ruled out which could increase the risk of a crash.

Remedy: An authorized Mercedes-Benz or Freightliner Sprinter dealer will add a supplementary booklet with a correct description of the Auto-P function to the Operator's Manual, which is already in the vehicle. The supplementary booklet is also available on-line at www.mbvans.com/sprinter/owners-resources/owner-manuals and https://www.freightlinersprinterusa.com/freightliner/owners-resources/owner-manuals.

05/19/2020

Mercedes-Benz USA LLC

Manufacturer Safety recall issued

- NHTSA #20V181
- Recall #2020040023
- Status: Remedy Available

Click here or call 1-800-367-6372 to locate an authorized Mercedes-Benz dealer near you to obtain more information about this recall

Learn more about this recall

Description: Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz and Freightliner vans, has determined that on certain Sprinter vehicles the rear part of the fender liner on the front axle could contact and chafe the brake hose. If the distance between the fender liner and the brake hose is not sufficient, the front wheel suspension could contact and chafe the brake hose, which could lead to the loss of brake fluid. Over time, if the operator ignores the brake fluid warning indicator and continues to operate the vehicle until the brake fluid empties, this may increase the stopping

distance and increase the risk of a crash. An authorized Mercedes-Benz or Freightliner Sprinter dealer will check the condition and clearance of the brake hoses and, if necessary, to replace them. Additionally, the corresponding fender liner will be modified accordingly on the respective side.

If the distance between the fender liner and the brake hose is not sufficient, the front wheel suspension could contact and chafe the brake hose, which could lead to the loss of brake fluid. Over time, if the operator ignores the brake fluid warning indicator and continues to operate the vehicle until the brake fluid empties, this may increase the stopping distance and increase the risk of a crash.

Remedy: An authorized Mercedes-Benz or Freightliner Sprinter dealer will check the condition and clearance of the brake hoses and, if necessary, to replace them. Additionally, the corresponding fender liner will be modified accordingly on the respective side.

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



## First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

A Junk Title is issued on a vehicle damaged to the extent that the cost of repairing the vehicle exceeds approximately 75% of its pre-damage value. This damage threshold may vary by state. The majority of states use this title to indicate that a vehicle is not road worthy and cannot be titled again. Some states treat Junk titles the same as Salvage.

When someone leases a car from a dealer, the dealer actually sells the vehicle to a leasing company. The leasing company then collects payments for the vehicle from the new owner for 24, 36, 48 or more months. A leasing company can be an independent car dealer or a car manufacturer.

### Manufacturer Recall

Automobile manufacturers issue recall notices to inform owners of car defects that have come to the manufacturer's attention. Recalls also suggest improvements that can be made to improve the safety of a particular vehicle. Most manufacturer recalls can be repaired at no cost to you.

**Ownership History** 

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

## Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



facebook.com/CARFAX



@CarfaxReports



CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. CARFAX®

© 2020 CARFAX, Inc., a unit of IHS Markit. All rights reserved. Covered by United States Patent Nos. 7,113,853; 7,778,841; 7,596,512, 8,600,823; 8,595,079; 8,606,648; 7,505,838. 5/22/20 7:51:01 AM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2019 MERCEDES-BENZ SPRINTER vehicle (VIN: WDAPF4CD8KN027149), which is based on information supplied to CARFAX and available as of 5/22/20 at 8:51 AM (EDT).						
Customer Signature	Date	 Dealer Signature	 Date			